

DIVISION OF OIL, GAS AND MINING



Michael O. Leavitt Governor

Ted Stewart **Executive Director**

James W. Carter Division Director

1594 West North Temple, Suite 1210

(801) 359-3940 (Fax)

Box 145801 Partial: XXX Complete: Exploration:

Salt Lake City, Utah 84114-5861 Spection Date & Time: 3/25/98 / 8:00a.m.-12:00p.m. (801) 538-5340

Date of Last Inspection: 2/23/98

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025						
Permittee and/or Operator's Name: Co-Op Mining Company						
Business Address: P. O. Box 1245, Huntington, Utah 84528						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Charles Reynolds						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Partly Cloudy, Warm, 60's, Rain in Forecast						
Existing Acreage: Permitted-1032.75 Disturbed-24 Regraded-0 Seeded-0 Bonded-24						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOLL COLORAL ANGER	EVALUATED [XX] [XX] [XX]	<u>N/A</u> [_] [_] [_]	COMMENTS [XX] []	NOV/ENF
4. a.	HYDROLOGIC BALANCE: DIVERSIONS	[XX]	f 1	[XX]	[]
b.	SEDIMENT PONDS AND IMPOUNDMENTS		H	[XX] [XX]	<u> </u>
c.	OTHER SEDIMENT CONTROL MEASURES	[XX] [XX]	Ħ		7
d.	WATER MONITORING	[]	Ħ	Ħ	Ħ
e.	EFFLUENT LIMITATIONS	Ħ	Ħ	Ħ	7
5.	EXPLOSIVES	Ti .	Ħ	Ti .	ា
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	Ħ	$\overline{[XX]}$	Π	፲፲
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	ī	[XX]		\Box
8.	NONCOAL WASTE	$\overline{[XX]}$			\Box
9.	PROTECTION OF FISH, WILDLIFE AND		_		
	RELATED ENVIRONMENTAL VALUES	[]		П	Ш
10.	SLIDES AND OTHER DAMAGE		$\overline{[XX]}$	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	[XX]	Π	\Box
12.	BACKFILLING AND GRADING	\Box	[XX]		\Box
13.	REVEGETATION	Ξ	[XX]	ĹĬ	ĹÌ
14.	SUBSIDENCE CONTROL	ĹΪ		\Box	\Box
15.	CESSATION OF OPERATIONS	[XX]	\Box	\Box	\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	\Box	[XX]	\Box
b.	DRAINAGE CONTROLS	[XX]	\Box		\Box
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box	\Box	\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]		\Box	
19.	AVS CHECK (4th Quarter-April, May, June)(date)	Ш	\Box	\Box	\Box
20.	AIR QUALITY PERMIT	[XX]	\Box	[XX]	\Box
21.	BONDING & INSURANCE	ַ ו ַ זַ	[]	[]	[]



INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 3/25/98

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The final approval of the mining plan for Federal lease U-024316 by the Secretary of the United States Department of the Interior is pending. This will permit coal extraction from this lease through the Tank Seam or Bear Canyon #2 Mine.

Mr. Reynolds informed me this day that a permit amendment to remove culvert C-2D from the Bear Canyon hydrology plan and add a minor change to the disturbed area boundary will probably be mailed today. This amendment will be ACT/015/025-98A.

4a. HYDROLOGIC BALANCE: DIVERSIONS

Due to the unseasonably warm weather during the past week (50 to 60 degrees F), most of the snow that was on site last month has now melted. The permittee has managed to dress up several of the road side diversions, but others still need work. This is part of the annual spring clean up; fix up, dress up is a normal part of mine operations for this time of year.

4b. SEDIMENT PONDS AND IMPOUNDMENTS

The permittee intends to re-initiate the cleaning of sediment pond "B" next week. As noted in the January and February, 1998 inspection reports, this pond is in dire need of cleaning.

16a. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Today's inspection revealed that the permittee has made very recent efforts to blade portions of the access road to the #1 and #2 Mines. Some diversions remain snow packed or frozen and as such, are not redefinable. At least one area of the Tank Seam access road was not bladeable due to excess mud.

20. AIR QUALITY PERMIT

The run-of-mine coal stockpile pad had large piles surrounding each of the various stacking tubes. The piles appeared to be dry. Although no wind was apparent at the time, it was suggested that the water sprays for these piles be turned on. Mr. Reynolds indicated that the sprays had probably not been turned on due to the uncertainty of temperatures for this time of year.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory progr	ram of the Division of Oil, Gas, and Mining.
Copy of this Report:	
Mailed to: Charles Reynolds (Co-Op)	Henry Austin (OSM)
Given to: Joe Helfrich (DOGM)	Filed to: Price Field Office
Date: March 25, 1998	
$\mathcal{A} / \mathcal{A} $	
Inspector's Signature:	#46
Peter Hess	